

CNX-LST - LED Linear Strip Light Installation Instructions

WARNING


- Before installation, make sure the input voltage is consistent with the fixture input voltage specifications.
- Thoroughly inspect the fixture for any freight damage.
- Disconnect power during installation and before servicing.
- Do not install on unstable, newly plastered or damp surfaces.
- All work should be performed by a qualified electrician.
- If you do not understand these instructions, please consult your local distributor.

Surface Mount Option


Step 1:

Turn off power from circuit breaker before connecting. Unpack the product and check that you have all the tools to install the luminaire safely and in compliance with any applicable electrical standards. Ensure the area is clear and free from any obstructions.

Turn OFF the circuit breaker



(b) Follow the diagram below to connect the power cables into the 2-way push connector and the ground wire using a twist wire connector (not provided). Make sure all conductors are fully sleeved and insulated.



(c) Replace the wiring cover.


Step 2:

Mark the surface, drill and fix the expansion screw.




Step 4:

Match the installation hole with the expansion screw, move the luminaire in a horizontal direction (left or right) so that it is fully secured.




Step 3:

(a) Remove the wiring cover.



Step 5:

Turn on main breaker



Turn ON the circuit breaker